


Technical bulletin

TB-076

Important Notification

After fitting this new alternator the warning light can stay on. This can be caused by connecting the lamp terminal to the wrong pin on the regulator and the warning light won't switch off. Please ensure that the vehicles wiring is connected to the alternator plug as shown in the diagram below.



IMPORTANT

Avoid short circuit between regulator pins.