



Technical bulletin

TB-093

FORD MONDEO / VOLVO V60, V70, S80 / LANDROVER FREELANDER



Check for fouling issues before fitting

Please note that in the above pictures, the damage to the rack's outer casing is due to a fitting issue.

If this type of damage occurs during fitment, then the steering will feel tight during operation.

On removal of the rack, if indeed this type of damage has occurred, the warranty could be rejected.