

Technical bulletin

TB-002

Before fitting this alternator, please check that there are no oil leaks on the engine, particularly around the alternator mounting area. This alternator is liable to suffer internal damage from liquid ingress, particularly oil, water or diesel.

