



Remy Europe



Technical bulletin

TB-058

Problems with the ignition switch and/or wiring harness on this application may cause the battery warning lamp to remain illuminated.

This problem will result in low battery voltage.

If the battery warning lamp is remaining illuminated, then check the vehicles switch and/or wiring before attempting to fit a replacement alternator.