



Remy Europe



## Technical bulletin

---

**TB-082**

### Important Notification

Before installation of this starter it is very important to compare the old starter you removed from the vehicle with the new starter.

Please count the teeth on the pinion. If your old starter has 10 or 11 teeth then you need to use the starter DRS7260.

In case you will install this starter which has 12 teeth and lower power you risk early live failure on your new starter.

Remy will not accept any warranty caused by not following this instruction.