



Remy Europe



Technical bulletin

TB-081

Important Notification

Before installation of this starter it is very important to compare the old starter you removed from the vehicle with the new starter.

Please count the teeth on the pinion. If your old starter has 12 teeth then you need to use the starter DRT1360.

In case you will install this starter which has 10 or 11 teeth you risk damages on your new starter and on the ring gear of your vehicle.

Remy will not accept any warranty caused by not following this instruction.