


## Technical bulletin

## TB-089

### Application guideline for 913869 starter motor

The 913869 units use 2 different drive designs with two different number of teeth: 10T and 12T



The OFFSET DE. BRACKET MITSUBISHI UNITS are with 12T pinion:

M2T87371 = MD331137

M2T88071 = MD344183

The NON-OFFSET DE. BRACKET MITSUBISHI UNITS are with 10T pinion:

M2T84170

M2T84171, -ZT = MD315547

M2T84571

M2T87171, -ZT = MD315548

The VALEO KOREA UNITS are with 10T pinion:

TM000A34101 = 36100-42250

TM000A36101 = 36100-42350

Although the replacement unit may appear to be different than the one removed from the vehicle, it will fit correctly to the application.