

## Technical bulletin

---

## TB-085

### ATTENTION!

This Technical Bulletin is for power steering racks fitted with a NON RETURN VALVE (See picture).

Please ensure that the one way valve is present within this steering rack port before fitting your replacement rack to the vehicle.

Should the valve be missing, remove (Note the position) and clean the original from the old unit, taking care not to damage the valve or port.

When re-fitting the valve to your replacement rack, ensure that the valve is free from damage and that it placed into the correct port.

Failure to do so could cause damage to the steering rack and may invalidate your warranty.

