



Remy Europe



Technical bulletin

TB-068

Important Installation Instruction

Before building in the new starter to avoid it over cranking due to the switch, please check the ignition switch that it works well.