

Technical bulletin

TB-088

Application Guideline for Mercedes Atego starters

Mercedes uses 2 different suppliers for the starter of the OM904 and OM906 engines:

1. BOSCH: 0001231002, 0001231033 / 0986017240
MERCEDES: A0041518401, A0051512001, A0061512201, A0061512203
2. DELCO REMY: 8200138, 8200297
MERCEDES: A0061512101, A0061516701

Although externally the 2 starters look different, the REMY type can replace the BOSCH starter.

Note: inspect the ring gear before installing the replacement Remy starter motor.

During inspection of the ring gear, if there is evidence of damage, or heavily worn teeth, then replace the ring gear.



Your warranty could be invalidated if the bad ring gear damages the starter motor.