



# Technical bulletin

# TB-096

## Application guideline for 913903, 913976 and 910085 starter motors

The DRS3903 is linked to only the 1.4HDI engine.

The DRS3976 and DRS0085 are linked to only the 1.6HDI engine.

The DRS3903 1.4kW starter fits only on the PSA 1.4HDI engines.

The below OE (Original Equipment) and OEM (Original Equipment Manufacturer) numbers are replacable with DRS3903:

428000-1640	DENSO	5802Y4 PSA
D6RA110	VALEO	5802AZ PSA
TS14E110	VALEO	5802FG PSA
MOT22472	MITSUBISHI	5802FH PSA
MOT93581	MITSUBISHI	5802FP PSA
MOT93582	MITSUBISHI	

The DRS3976 1.5kW and DRS0085 2.2kW starters fit only on the PSA 1.6HDI engines.

The below OE (Original Equipment) and OEM (Original Equipment Manufacturer) numbers are replacable with DRS3976:

D7G3	VALEO	5802Z8 PSA
TS18E13	VALEO	5802EG PSA
MOT22471	MITSUBISHI	
MOT22473	MITSUBISHI	

The below OE (Original Equipment) and OEM (Original Equipment Manufacturer) numbers are replacable with DRS0085:

D7G26	VALEO	5802AE PSA
TS22E26	VALEO	5802CE PSA